

RhinoCAM

2½ Axis Machining

2025

Introduction

MecSoft Corporation
© Copyright 1998-2025

Table of Contents

Introduction	4
What is 2½ Axis Machining	6
Machining Regions	7
The Tutorial Part	9
Machining Job & Setup	10
2½ Axis Face Top	11
2½ Axis Engraving	20
2½ Axis Pocketing (Blind Pockets)	26
2½ Axis Pocketing (Thru Holes)	35
2½ Axis Profiling	41
Cut Material Simulation	49
Posting G-Code	50
Index	53

Introduction

 In this tutorial you will get an introduction to 2½ Axis milling. You will learn the basics of 2½ Axis machining including Machining Regions, the Setup, Facing, Engraving, Profiling, Cut Material Simulations and more. 

Source Files for this Tutorial

Here are the links to download the source files used in this tutorial:

- [AMS-MecSoft-CAM-2axis-Intro.zip](#)

Guides & Videos in this Series

We also suggest that you complete the following companion tutorials and videos in this series:

- Tutorial: 2½ & 3 Axis Setups
- Tutorial: 2½ Axis Introduction
- Tutorial: 2½ Axis Advanced (AMS/Purchase Only)
- Tutorial: 2½ Axis Power Users (AMS/Purchase Only)
- Video: 2½ Axis Introduction
- Video: 2½ Axis Advanced (AMS/Purchase Only)
- Video: 2½ Axis Power Users (AMS/Purchase Only)

Other Supplemental Videos

We also suggest that you watch the supplemental videos on MecSoft.com:

[RhinoCAM-MILL product page](#)

[VisualCAM-MILL product page](#)

The Quick Start Guide

This tutorial assumes that you are familiar with how to load the [MILL](#) module and that you have previously completed the [MILL Quick Start Guide](#). You can find this guide by selecting Learn ... from the [MecSoftCAM Main Menu](#).

In RhinoCAM:



What is 2½ Axis Machining

 2½ Axis machining is the 2nd most common application (behind 3 Axis machining) for MecSoft CAM users. The reason for this is because a large number of parts found in the real world lend themselves to 2½ Axis machining. That is to say, that the majority of 2½ Axis components are simple prismatic shapes composed of drilled holes, flat horizontal faces and straight or drafted vertical walls.


In 2½ Axis machining the cutter moves in a plane both in the X and Y direction while maintaining a fixed Z height. The ½ axis is appended to 2 Axis, to denote the fact that cutting is done in successive fixed Z height planes starting at the highest Z level and stopping at a lowest Z level, thereby machining a complete 3D prismatic part.

2½ Axis Part Examples




Machining Regions

 Here is a recap of some best practice methods regarding Cut levels and Machining Regions in 2½ Axis machining:




✓ Understand how Radius Mills behave near an edge

It is important to understand how Z heights AND the XY perimeter of each machining region are honored by radius cutting tools. We have reduced the cut level in the following example to illustrate the waterfall effect of the Ball Mill tool as it makes contact with the edge of the machining region.





✓ Understand Nested Machining Regions

It is important to understand how Z heights AND the XY perimeter of each machining region are honored by radius cutting tools. We have reduced the cut level in the following example to illustrate the waterfall effect of the Ball Mill tool as it makes contact with the edge of the machining region.




✓ The proper use of Avoid Regions

Avoid Regions are typically used to avoid objects such as clamps and fixtures. When using Avoid Regions make sure they overlap the Machining Regions as shown in the examples below. They can be selected from the Avoid Regions tab on the Control Geometry section of the Facing, Pocketing and Profiling toolpath dialog.



The Tutorial Part

 In this tutorial 2½ Axis toolpaths are used to program a simple prismatic part from 2024 Aluminum. The part measures 14.28" long, 3.46" wide and 0.748" high and will be machined from 3/4" plate stock measuring 15" x 3.5" x 0.75" using the Fanuc0m controller. The part features include blind pockets, through hole pockets and a perimeter profile. The part is also engraved with a part number. The Machining Jog tree for the part is shown above. The machinable features are shown in the illustration below.



Machining Job & Setup

 The Machining Job tree for this project is shown below. The Machine definition is set to 3 Axis, The Post definition is set to Fanuc0m, and the Stock is set to Box Stock measuring 15" x 3.5" x 0.75". The stock is aligned flush with the bottom of the part and Stock Material is set to ALUMINUM-6061. Setup 1 is at its default location which is coincident with the WCS World Origin. A Work Zero is defined and is located the top south west corner of the stock. Fixtures are set to None. Refer to the companion tutorial [How to Define a Setup for 2½ / 3 Axis Milling](#) for the basic steps to complete the Machining Job tree and Setup 1 as described here.

The Machining Job tree and part now looks like this.




2½ Axis Face Top



The first machining operation is the setup is a 2½ Axis Facing toolpath.

This will ensure the top of the stock is flat with the top of the part. The top face of the part is at Z0.748 and is flat parallel to the XY plane. With this operation a 2.50" diameter x 0.50" face mill is used. Parameters include a Tolerance of 0.01 and Stock value of zero, a mixed cut direction, linear cut pattern, and 50% stepover. The Location of Cut Geometry is set to At Top with a cut depth of zero (one pass). Facing Entry/Exit is set to Lines & Arcs, a Tangent Approach Motion Length of 0.25 and zero radius and the same for the Departure Motion. Clearance is set to Automatic. You refer to the illustration below.



2½ Axis Facing Procedure

Here are the basic steps to create the 2½ Axis Facing toolpath strategy shown above. The dialog images show the parameters used. In most cases the default values are used. Pay close attention to the parameters on the Control Geometry, Roughing and Cut Level tabs.

1. New operations are generated BELOW the selected operation in the Machining Job tree so first make sure the Work Zero is selected.




- From the **Program** tab select the **2 Axis** menu and then pick **Facing**.



- From the **Control Geometry** tab pick **Remove All** if there previous regions listed. In **Facing** if you do not select **Part Regions**, the entire part is calculated for the XY extents of the facing operation. Check the box to **Include stock model silhouette** and then select the **Tool** tab.



- From the **Tool** tab select the **Edit/Create/Select Tool ...** button to display the Create/Select Tool dialog.



- Use the parameters shown in the dialog below to define a **Face** mill cutting tool. Here are the basic steps:

A: Select **Face Mill** from the top toolbar.

B: Enter "**FACEMILL-2.5 INCH**" for the **Name**.

C: Enter the **Tool** dimensions shown in the dialog below paying attention to the tool preview window.


D: Complete the **Properties** sections as shown.

E: Select the **Feeds & Speeds** tab and enter the desired values.


F: Then select **Save as New Tool** and you will see that the tool is added to the **Tools in Session** list on the left side of the dialog.




6. Now pick **OK** from the Create/Select Tool dialog and you will see that your tool is added to the **Tools** list of the Tools tab in the 2 Axis Facing dialog.



7. Since it is the only tool, it will be selected by default for this operation. Now select the Feeds & Speeds tab of the dialog.
8. The feeds & speeds allow you to set you feeds and speeds for this operation only. To load the feeds & speeds that you set for the tool, pick the **Load from Tool** button. To calculate new feeds & speeds values you can pick the **Load from File** button and use the built in Feeds & Speeds Calculator.



- Now select the **Clearance Plane** tab of the **Facing** operation dialog. We will use the default values for clearance. The Clearance Plane Definition is set to **Automatic** and the **Cut Transfer Method** is set to **Clearance Plane**. At any time you can select the **Help** button from the dialog to display the online help for this dialog.




10. Now select the **Roughing** tab from the dialog. Here you can set global parameters, the cut pattern, cut direction and stepover parameters.



11. We are using a **Linear Cuts**, **Mixed** cut direction, a **Stepover** distance of 50% of the tool diameter and we are starting at the bottom of the cut (i.e., negative Y direction).




12. Now select the **Cut Levels** tab of the dialog. Here we have the **Location of Cut Geometry** set to **At Top** and the **Total Cut Depth**, **Rough Depth**, **Finish Depth**, **Rough Depth/Cut** and **Finish Depth/Cut** all set to zero. This means that there will be only one cut level located at the top of the part.




13. Now select the **Facing Entry/Exit** tab of the dialog. Here you can determine how the cutter will approach and engage the cut pattern as well as how it will depart and retract. We have the **Entry Motions** set to **Lines & Arcs**, Approach Motion set to **Tangent** and **Length (L)** set to 0.5. The **Engage Motion** is set to **Radial** and **Radius (R)** set to zero. These parameters will extend the entry motion tangent to the cut start point of the cut pattern by 0.5”.





14. We also have the **Exit Motions** set to **Lines & Arcs**, **Departure Motion** set to **Tangent** and **Length (L)** set to 0.5. The **Retract Motion** is set to **Radial** and **Radius (R)** set to zero. These parameters will extend the exit motion tangent to the last cut point in the cut pattern by 0.5”.



© 2025 MecSoft Corporation




16. Now pick **Generate** and the 2½ Axis Facing toolpath is calculated and displayed on the part. It is also listed in the **Machining Job** under the **Work Zero**.



2½ Axis Engraving


 The part number "PN MS-20" is engraved onto the top face of the part as shown using the **2½ Axis Engraving** toolpath method with a 0.50" diameter x 45 degree Vee mill. The **Location of Cut Geometry** is set to **At Top**, **Tolerance** is 0.001" and **Total Cut Depth** is 0.02" at one pass. **Entry/Exit** is set to **None**. **Cut Arc Fitting** is enabled with a **Fitting Tolerance** of 0.002". Sorting is set **Minimum Distance Sort**.



2½ Axis Engraving Procedure

Here are the basic steps to create the **2½ Axis Engraving** toolpath strategy shown above. The dialog images show the parameters used. In most cases the default values are used. Pay close attention to the **Cut Parameters** tab.

1. New operations are generated **BELOW** the selected operation in the **Machining Job** tree so first make sure the previous **2½ Axis Facing** operation is selected.




2. From the **Program** tab select the **2 Axis** menu and then pick **Engraving**.




3. From the **Control Geometry** tab pick **Remove All** if there previous regions listed. We want to add the text curves to this dialog. To do this pick the **Select Curve/Edge Regions** button and the dialog will minimize while you select the text curves. When they are selected, **right-click** or press **<Enter>** and the dialog will reappear with the geometry listed in the **Part Regions** section under **Selected Machining Region(s)**. It may be easier to select the text from the **Top** view as shown below. Make sure **ONLY** the text curves are selected.






4. Now select the **Tool** tab and pick the **Edit/Create/Select Tool ...** button to display the **Create/Select Tool** dialog.



- Using the Create/Select Tool dialog select the Vee Mill icon from the toolbar at the top of the dialog and then enter the name and dimensions as shown in the dialog below. You can also edit the feeds and speeds by selecting the [Feeds & Speed](#) tab. When done, pick the [Save as New Tool](#) button and the tool will be listed in the [Tools in Session](#) list on the left. Now pick [OK](#) to close the [Tools](#) dialog.



- The new tool [VEE-45 DEG](#) is listed in the Tools list of the dialog. Select it as the active tool and then pick the [Cut Parameters](#) tab. Notice that we skipped the [Feeds & Speeds](#) tab and the [Clearance Plane](#) tab. We are using the default setting on these tabs. Refer to the [2½ Facing](#) steps above to see these two tabs in more details.



- From the [Cut Parameters](#) tab we will use the default parameter values except for the [Cut Depth Control](#) section of the dialog. Location of Cut Geometry is set to At Top because our text curves are located at the top of the cut. The changes to the parameters listed below will make one cut

level at -Z0.02 for each of the text curves selected.

The following parameters should be revised:


A: Set the Total Cut Depth to 0.02.

B: Set the [Rough Depth](#) to 0.2.

C: Set the [Rough Depth/Cut](#) to 0.2 also.


D: Set the [Finish Depth](#) to 0 (zero).

E: Set the [Finish Depth/Cut](#) to 0 also.




8. We will skip the [Entry/Exit](#) and the [Advanced Cut Parameters](#) tabs to use those default values. Now we select the [Sorting](#) tab and select [Minimum](#)

Distance Sort for the sorting method and the Start Point to Lower Left. Now pick **Generate** to calculate the engraving toolpath, display it on the part and also list it in the **Machining Job** tree as shown below.



2½ Axis Pocketing (Blind Pockets)


 The two blind pockets are cut using the **2½ Axis Pocketing** toolpath method with a 0.50" diameter flat end mill. **Tolerance** is set to 0.01 and **Stock** is zero, an Offset cut pattern, **Mixed** cut direction, **Inside** start point and a **Stepover** of 25%. For **Cut Levels**, **Location of Cut Geometry** is set to **At Top**, a **Total Cut Depth** of 0.551" split into two cut levels of 0.275". **Depth First** is enabled meaning pocket 1 will be cut to depth before pocket 2 is started. **Pocketing Entry** is set to **Path** (Ramp) at a Height of 0.05" and an angle of 10 degrees. Retract is set to **Linear** and **Entry/Exit** is applied to each cut level. **Cut Arc Fitting** is enabled.



2½ Axis Pocketing Procedure

Here are the basic steps to create the **2½ Axis Pocketing** toolpath strategy shown above. The dialog images show the parameters used. In most cases the default values are used. Pay close attention to the **Cut Parameters**, **Cut Levels** and **Pocketing Entry/Exit** tabs.

1. New operations are generated BELOW the selected operation in the **Machining Job** tree so first make sure the previous **2½ Axis Engraving** operation is selected.



2. From the **Program** tab select the **2 Axis** menu and then pick **Pocketing**.



3. From the **Control Geometry** tab pick **Remove All** if there previous regions listed. We want to add the face edges located at the top perimeter of both pockets to this tab of the dialog.

Select the **Part Regions** sub tab and then pick the **Select Curve/Edge Regions** button. The dialog will minimize and prompt you to select curve of surface edges. **Chain Select** the edges shown below that form two closed loops.



How to Chain Select in Rhino:

Pick the **Select** command tab in **Rhino** and then pick the **Select Chain** icon:




In the **Rhino** command prompt, make sure **Chain Continuity** is set to **Tangency**.






4. Now select the **Tool** tab and pick the **Edit/Create/Select Tool ...** button to display the **Create/Select Tool** dialog.




5. Using the **Create/Select Tool** dialog select the **Flat Mill** icon from the toolbar at the top of the dialog and then enter the name and dimensions as shown in the dialog below. You can also edit the feeds and speeds by selecting the **Feeds & Speeds** tab. When done, pick the **Save as New Tool** button and the tool will be listed in the **Tools in Session** list on the left. Now pick **OK** to close the **Tools** dialog.




6. The new tool **FLATMILL-½ INCH** is listed in the **Tools** list of the dialog. Select it as the active tool and then pick the **Cut Parameters** tab. Notice that we skipped the **Feeds & Speeds** tab and the **Clearance Plane** tab.


We are using the default setting on these tabs. Refer to the [2½ Facing](#) steps above to see these two tabs in more details.




7. Now select the [Cut Parameters](#) tab. Set the [Cut Pattern](#) to [Offset](#), [Cut Direction](#) to [Mixed](#), [Start Point](#) to [Inside](#), [Stepover Distance](#) to 25% as shown in the dialog below.



8. Now select the **Cut Levels** tab and set the **Location of Cut Geometry** to **At Top**.




9. For the **Total Cut Depth**, select the **Pick** button . This will minimize the dialog and allow you to select two points from the part model to use to calculate the **Total Cut Depth**. Set the **Object Snap** to **Endpoint** and select the two endpoints shown below. The **Cut Levels** tab will display once again with the **Total Cut Depth** value entered into the dialog. The **Total Cut Depth**, **Rough Depth** and **Rough Depth/Cut** will all be set to the same calculated depth value.




10. Now for the **Rough Depth/Cut** use the slider to change the value to approximately 0.275".
11. The **Finish Depth** and **Finish Depth/Cut** should be 0 (zero). Now for **Cut Levels Ordering** select **Depth First** and then pick the **Pocketing Entry/Exit** tab to continue.



12. We will be using a ramp entry and linear retract motions. The **Approach Motion Length (L)** is set to 0.025, the **Engage Motion** is set to **Path** with **Angle (A)** set to 10 and **Height (H)** set to 0.05. The **Retract Motion** is set to **Linear** with **Length (L)** set to 0.0625 and **Angle (A)** set to 45 degrees. Also, **Departure Motion Vertical Distance (D)** is set to 0.025. Now pick **Generate** to calculate the pocketing toolpath, display it on the part and also list it in the **Machining Job** tree as shown below.



13. In 2½ Axis Pocketing an additional display toggle icon appears on the **Machining Job** toolbar (at the bottom). Select it to display the **Z Level Display** dialog that allows you to select and view each cut level in the **Pocketing** operation as shown below.

**Toolpath Visibility** Toggle Toolpath Visibility

2½ Axis Pocketing (Thru Holes)

-  The two through holes are also cut using the 2½ Axis Pocketing operation. All cut parameters are the same as the blind pockets except for [Cut Levels](#). The [Total Cut Depth](#) is set to 0.748" and three cut levels, the first at 0.299 deep as shown in the illustrations below.



2½ Axis Pocketing Procedure

Here are the basic steps to create the 2½ Axis Pocketing toolpath strategy shown above. The dialog images show the parameters used. Again, in most cases the default values are used. Pay close attention to the [Cut Levels](#) and [Pocketing Entry/Exit](#) tabs.


1. From the [Program](#) tab select the [2 Axis](#) menu and then pick [Pocketing](#).




2. From the [Control Geometry](#) tab pick [Remove All](#) if there previous regions listed. We want to add the face edges located at the top perimeter of both thru holes to this dialog.

To do this, pick the [Select Curve/Edge Regions](#) button and the dialog will minimize while you select the face edges shown below. Use [Chain Select](#) to select these edges and when done, [right-click](#) or press [<Enter>](#) to accept the selections and display the dialog again. Your selections are listed in the [Part regions](#) section of the dialog.







- We will use the same 1/2" diameter flat end mill from the last operation. Select the **Tool** tab and then select the **FLATMILL-1/2 INCH** tool and then proceed to the **Cut Parameters** tab.



4. From the **Cut Parameters** tab set the **Cut Pattern** to **Offset**, **Cut Direction** to **Mixed** and **Stepover Distance** to 25% as shown in the dialog below.





- Now move to the **Cut Levels** tab and set the **Total Cut Depth** to the height of the part. Just like the last pocketing operation, use the **Pick** button  and select two points to detect the total height of the part. The **Total Cut Depth**, **Rough Depth** and **Rough Depth/Cut** should calculate to approximately 0.748". Now for the **Rough Depth/Cut** use the slider to adjust the value to 0.299". For **Cut Levels Ordering** select **Depth First**.



6. The values in the [Pocketing Entry/Exit](#) tab should be the same as the previous pocketing operation. These values are shown below. You can see the ramp entry motions in the illustrations above.



7. Now pick [Generate](#) to calculate the [Pocketing](#) operation and display it on the part and in the [Machining Job](#) tree as shown below. To see hidden portions of the toolpath, select the [Toggle Hidden Areas Display](#) icon from the base of the [Machining Job](#) toolbar.



2½ Axis Profiling


-  The outer perimeter is cut using the 2½ Axis Profiling toolpath method with the same 0.50" flat end mill. **Tolerance** is 0.001" and **Stock** is zero. **Cut Direction** is set to **Climb**, **Cut Start** is set to the midpoint of the longest side with **Cut Side** set to **Outside**. For **Cut Levels**, the **Location of Cut Geometry** is set to **At Top**, a Total Cut Depth of 0.748" and three cut levels of 0.249". Entry/Exit is set to **Lines & Arcs**, with a **Tangent Approach** and **Radial Departure** motions at each cut level.




2½ Axis Pocketing Procedure

Here are the basic steps to create the **2½ Axis Profiling** toolpath strategy shown above. The dialog images show the parameters used. Again, in most cases the default values are used. Pay close attention to the **Cut Levels** and **Pocketing Entry/Exit** tabs.

1. New operations are generated **BELOW** the selected operation in the **Machining Job** tree so first make sure the previous 2½ Pocketing operation is selected.




2. From the **Program** tab select the **2 Axis** menu and then pick **Profiling**.




3. From the [Control Geometry](#) tab pick [Remove All](#) if there previous regions listed. We want to add the face edges located at the top outside perimeter of the part.

To do this, pick the [Select Curve/Edge Regions](#) button and the dialog will minimize while you select the face edges shown below. Use [Chain Select](#) to select these edges and when done, [right-click](#) or press [<Enter>](#) to accept the selections and display the dialog again. Your selections are listed in the [Part regions](#) section of the dialog.





4. We will use the same ½" diameter flat end mill from the last operation. Select the **Tool** tab and then select the **FLATMILL-½ INCH** tool and then proceed to the **Cut Parameters** tab.




5. From the **Cut Parameters** tab we will adjust the following parameters:

A: **Tolerance**: 0.001

B: **Cut Direction**: to Climb (Down Cut)


C: **Cut Start Point for Closed Curves**: Use Mid-Point of longest side

D: **Cutting Side**: Specify, Right of Curves, Use Outside/Inside for Closed Curves, Outside




6. Now move to the **Cut Levels** tab and set the Total Cut Depth to the height of the part. Just like the last pocketing operation, use the **Pick** button  and select two points to detect the total height of the part. The **Total Cut Depth**, **Rough Depth** and Rough Depth/Cut should calculate to


approximately 0.748". Now for the **Rough Depth/Cut** use the slider to adjust the value to 0.249" to produce 4 cut levels. **Finish Depth** and **Finish Depth/Cut** should be 0 (zero). For **Cut Levels Ordering** select **Depth First**. Refer to the dialog below.




- Now move to the **Entry/Exit** tab. Set the **Entry Motions** to Lines & Arcs. Then for **Approach Motion** select **Tangent** and then set **Length (L)** to 0.25. For **Engage Motion** select **Radial** and set **Radius (R)** to 0.25. You can refer to the illustration in the dialog for what these parameters mean. Your **Entry Motion** parameters should look like the dialog below.



8. Now set **Exit Motions** to Lines & Arcs also. Set the Retract Motion to **Radial** and then set **Radius (R)** to 0.25. For **Departure Motion** select **Tangent** and set **Length (L)** to 0.25 also. One additional setting. Check the box to **Apply entry/exit at each cut level**. Your **Exit Motion** parameters should look like the dialog below.



9. Now pick **Generate** to calculate the **Profiling** operation and display it on the part and in the **Machining Job** tree as shown below. To see hidden portions of the toolpath, select the Toggle **Hidden Areas Display** icon from the base of the **Machining Job** toolbar.




Cut Material Simulation

 Here are the basic steps to perform a cut material simulation of this setup.


1. From the [Machining Job](#) tree select [Setup 1](#).



2. Now select the [Simulate](#) tab and adjust the [Options](#) portion of the menu. You can use the slider to adjust the simulation speed. You can also uncheck [Simulate by Moves](#) to further slow down the simulation.



3. Now with [Setup 1](#) select, pick [Play](#) from the [Simulate](#) Tab.




4. The cut material simulation will play on the screen. Here is what the simulation will look like for this machining job.



Posting G-Code

-  Here are the basic steps to post G-Code files for our machining operations.


1. Switch back to the **Program** tab.




2. From the **Machining Job** tree select the operations that you wish to post a G-Code file for. If you have an automatic tool changer on your CNC machine you can post all operations in one file by selecting **Setup 1**.




3. If your CNC machine does not have an automatic tool changer, you can select one operation.




4. You can also select multiple operations from the **Machining Job** tree and post them to one G-Code file. For example, the last three operations use the same tool number, so they can be posted together.




5. After your operations are selected from the **Machining Job** tree, right-click and select **Post** from the menu.



6. The **Post & Save As** dialog will display. Enter a name for the posted G-Code file and then select Post.



7. The posted G-Code file will display in [Notepad](#) by default. You can change the program to open G-Code files in, by selecting [Post](#) from the [Program](#) tab and adjust the [Set Post-processor Options](#) dialog. Sample G-Code files are shown below in Notepad.



Congratulations, you have completed this tutorial!

Index

- 2 -

2½ Axis Examples 6

- C -

Chain Select 20
Clearance 11
Create/Select Tool 26

- E -

Engraving
About 20
Control Geometry 20
Cut Parameters 20
Entry/Exit 20
Feeds & Speeds 20
Generate 20
Menu Selection 20
Tool Selection 20

- F -

Facing (Top)
About 11
Advanced Cut Parameters Cut Parameters 11
Clearance 11
Control Geometry 11
Cut Levels 11
Entry/Exit 11
Feeds & Speeds 11
Generate 11
Menu Selection 11
Roughing Parameters 11
Tool Selection 11
Feeds & Speeds 11

- G -

Getting Ready 4

- M -

Machine 10

- P -

Pocketing (Blind Pockets)
About 26
Control Geometry 26
Cut Levels 26
Cut Parameters 26
Generate 26
Menu Selection 26
Pocketing Entry/Exit 26
Tool Selection 26

Pocketing (Thru Holes)
About 35
Control Geometry 35
Cut Levels 35
Cut Parameters 35
Generate 35
Menu Selection 35
Pocketing Entry/Exit 35
Tool Selection 35

Post 10
Posting G-Code 50

Profiling
Control Geometry 41
Cut Levels 41
Cut Parameters 41
Entry/Exit 41
Generate 41
Menu Selection 41
Tool Selection 41

- S -

Simulation 49
Stock
Part Box Stock 10
Z Offset 10

- T -

The Tutorial Part 9

- W -

What is 2½ Axis Machining 6
work Zero 10