

# Post-Processor (PPG) Decoded VisualCAD/CAM 2025

Published: February 2025

**N049** G0

**N050** G1Z-0. F29.334

**N051** G02Z-0.125I-0.4375J-0.0002 F14.667

**N052** G02Z-0.25I-0.4375J-0.0002

**N053** G02X-0.4375Y-0.0002I-0.4375J-0.0002

**N054** G02X0.4375Y0.0002I0.4375J0.0002

**N055** G0Z0.25

**N056** (Deep Drill)

**N057** ( Tool Diameter = 0.25 Leng

**N058** G20 T3 M6

**N059** G54

**N060** S190 M3

**N061** G90G0X0.75Y-0.75

MecSoft Corporation

© Copyright 1998-2025

# Table of Contents

<b>Quick Start</b>	<b>3</b>
<b>Resource Guide</b>	<b>6</b>
<b>Introduction</b>	<b>7</b>
1 What is a Post-Processor?.....	8
2 What is the PPG?.....	8
3 PPG Variables & Macros.....	9
<b>Decoding a Sample G-Code File</b>	<b>10</b>
1 The Setup & Post Processor.....	10
2 The Sample Toolpaths.....	10
3 The Posted Setup G-Code File.....	12
4 The 2½ Axis Profiling Operation G-Code.....	15
5 The 2½ Axis Hole Profiling Operation G-Code.....	19
6 The Deep Drilling Operation G-Code.....	21
<b>The Post-Processor Generator Dialog</b>	<b>24</b>
1 PPG > General.....	24
2 PPG > Start/End.....	25
3 PPG > Tool Change.....	28
4 PPG > Setup.....	32
5 PPG > Spindle.....	33
6 PPG > Feed Rate.....	34
7 PPG > Motion.....	36
8 PPG > Circle.....	37
9 PPG > Helical/Spiral.....	40
10 PPG > Multi Axis Motion.....	42
11 PPG > Cutter Compensation.....	43
12 PPG > Cut Motion Start/End.....	46
13 PPG > Cycles.....	47
14 PPG > Misc.....	50
15 PPG > Variables.....	52
<b>Index</b>	<b>53</b>

## Quick Start



# PPG Module 2025

[Prefer Printed Documentation? Click Here!](#)

[What's New](#) | [Quick Start Play List](#)

[Quick Start Guides](#) for each [VisualCAD/CAM](#) module are available in both PDF and Video format. Refer to the following information to access these resources:



### How to Access the Quick Start Guide Documents


To help you quickly get started in working with each module, select one of the Help buttons located on the [VisualCAD/CAM Learning Resources](#) dialog.

You will find:

- Quick Start Guides
- What's New documents
- Online Help links


The [Quick Start Guides](#) will help you step through an example tutorial which will illustrate how to use the module. To access the [Learning Resources](#) dialog:


1. From the [VisualCAD Home Ribbon Bar](#), drop down the Main menu and select [Learn ...](#)



To access the Learning Resources dialog in VisualCAM

2. Select a document from the [Learning Resources](#) dialog to get started using the module of your choice.

 You can also select the [Open Quick Start Files Folder](#) button located at the bottom of the dialog to open the [Quick Start](#) folder where the source files (start and completed versions) are located.



Learning Resources Dialog



## Related Topics


Find More Resources

## Resource Guide

Download this PDF Guide for a list of the available [VisualCAD/CAM Resources](#).



### 2025 VisualCAD/CAM Resource Guide



### The 2025 VisualCAD/CAM Resource Guide!

*18 Pages*


Lists PDF downloads and Online resources including [Quick Start Guides](#), [Reference Guides](#), [Exercise Guides](#), [Tutorials](#) and [More](#).


[Prefer Printed Documentation? Click Here!](#)


[What's New](#) | [Quick Start Play List](#)


## Introduction

This guide provides the basis for understanding how the [Legacy Post-Process Generator \(PPG\)](#) operates and how you can use it to customize your posted g-code files. It uses a simple part file example with three toolpath operations. Each toolpath is illustrated, examined and the resulting G-Code is color coded to the portion of the [PPG](#) that controls it. Each section of the [PPG](#) is then explained and examined for the part file example and its resulting G-Code.

 **NOTE:** This guide includes sample CAM files, toolpath operations, a customized Haas post definition file and the sample G-Code file. These source files are included in your CAMJam download archive.



 **Remember:** The PPG is your friend! It can save you and your CNC operator enormous amounts of time during production!





### 3.1 What is a Post-Processor?

The post-processor converts the toolpath operations you create in MecSoft CAM into a suitable format (called G-Code) that your CNC machine controller can interpret. The G-Code that MecSoft CAM's post-processors create adheres to [ISO6983](#) (the international standard for numerical controls). The post-processor also tailors the G-Code to a specific type of CNC controller such as [Haas](#), [Fanuc](#), [Mach3](#), [WinCNC](#), etc. MecSoft's CAM plugins come installed with over 300 post-processor definition files that are pre-configured for a wide range of CNC machines & controllers available on the market today.

### 3.2 What is the PPG?

The [Post-Processor Generator \(PPG\)](#) allows you to create and customize your post definition files. These files have the file extension of [\\*.spm](#). The names of these post definition files are what you are selecting when you define your post-processor. For example when you select [MILL > Program > Post](#) and select the [Haas](#) post-processor you can also select the [Edit ...](#) button and the [Post-Processor Generator](#) will display with the [Haas.spm](#) post definition file loaded for editing. The default folder where these files are stored is also listed just below the post selection. This is illustrated in the two dialog images below.





The Post-Processor Generator (PPG)

### 3.3 PPG Variables & Macros



The **PPG** uses hundreds of variables and macros that allow you to customize each post definition file. The names of the variables are pre-defined. The values for many of the variables are extracted from your CAM cutting tools, setups, toolpath operations, etc. Other variable values are defined within the **PPG** itself specific to the post definition file. Load the **PPG** and select Variables to see the complete name and value of each available variable. You can also use algebraic expressions within the **PPG**. Just pick the **Help** button from the **PPG** dialog to learn more.

## Decoding a Sample G-Code File

In this guide we will use the following sample part and toolpaths to see how internal variables for CAM definitions such as stock size, tool size, feeds & speeds parameters, toolpath operation types and various other cutting parameters, are used by the post-processor generator and the post definition file to define the format and output of the resulting G-Code file.


### 4.1 The Setup & Post Processor

The Machine is defined as **3 Axis** (this is used for both **2½ Axis** and **3 Axis** applications). The post-processor definition file selected is a Haas post that we have specifically customized for this article. The Haas machining center has an automatic tool changer. The post definition file is [haas-blog.spm](#). The stock is a 2-1/8" x 2-1/8" x 1/4" 6061 Aluminum plate. All sample files are included in the download archive at the end of this document.




### 4.2 The Sample Toolpaths

The sample toolpaths included in the test part are **2½ Axis Profiling** with Cutter Compensation and External Corners Loop using a ¼" diameter end mill, **2½ Axis Hole Profiling** with a helical path using a 1/8" diameter end mill and a **Deep Drilling** operation using a ¼" drill.



Sample Part: 2½ Axis Profiling

Sample Part: 2½ Axis Hole Profiling



Sample Part: Deep Drilling


### 4.3 The Posted Setup G-Code File

We right-clicked on the [Setup](#) and selected [Post](#) to output one G-Code file that includes all three machining operations. The G-Code file is shown below. We have color-coded each line of the G-Code file to its corresponding section in the [PPG](#).


The [PPG](#) we have selected (*haas-blog.spm*) directs the format and content of code. Using these three toolpaths you see that in the 70 lines of code 12 of the 15 [PPG](#) sections are working together to define the G-Code file. The [PPG](#) sections are shown in the image below. Again, we have color-coded each section to help you identify each line in the G-Code file.

Three [PPG](#) sections are not represented in this G-Code sample. They are listed below along with the reason why. However these sections are discussed in this article.

1. [Setup](#): This is used for 4 and 5 Axis setups only. It does not affect our G-Code sample file.
2. [Multi-Axis Motion](#): Again, this is used for 4 and 5 Axis setups only. It does not affect our G-Code sample file.
3. [Cut Motion Start/End](#): This [PPG](#) section is not required for our G-Code sample file.



PPG Dialog Selections



Highlight Setup, right-click and select Post

```

%
O1234
N001 G40 G49 G80
N002 ( STOCK SIZE: X2.125 Y2.125 Z0.25 )
( BEGIN TOOL LIST )
( TOOL 1 - FlatMill:0.25 - DESC: 0.2500 DIA, 2 FLUTE, CARBIDE MAT )
( TOOL 2 - FlatMill:0.125 - DESC: 0.1250 DIA, 2 FLUTE, CARBIDE MAT )
( TOOL 3 - Drill: 1/4" - DESC: 0.2500 DIA, 2 FLUTE, CARBIDE MAT )
( ENDOF TOOL LIST )
N003 (Setup 1)
N004 (Work Zero)
N005 G54
N006 (2 1/2 Axis Profiling (Outer))
N007 ( Tool Diameter = 0.25 Length = 2.0 )
N008 G20 T1 M6
N009 S10000 M3
N010 G90G0X-1.2533Y-0.3524
N011 G43Z0.25H1
N012 M8
N013 G0
N014 G1Z-0.25 F97.5
N015 G41 G1 X-1.2533 Y-0.3524 D1 F146.25
N016 G1X-1.1678Y-0.1175
N017 G1X-1.125Y0.
N018 G1Y1. F195.
N019 G1Y1.25
N020 G17
N021 G03X-1.25Y1.125I-0.125J0.
N022 G1X-1.
N023 G1X1.
N024 G1X1.25
N025 G03X1.125Y1.25I0.J0.125
N026 G1Y1.
N027 G1Y-1.
N028 G1Y-1.25
N029 G03X1.25Y-1.125I0.125J0.
N030 G1X1.
N031 G1X-1.
N032 G1X-1.25
N033 G03X-1.125Y-1.25I0.J-0.125

```

The first half of the complete G-Code file (79 lines) is shown color coded to each PPG section that controls it.


```

N033 G03X-1.125Y-1.25I0.J-0.125
N034 G1Y-1.
N035 G1Y0.
N036 G1Y0.1
N037 G1X-1.2105Y0.3349 F243.75
N038 G40
N039 G1X-1.296Y0.5698 F292.5
N040 G0Z0.25
N041 (Hole Profiling)
N042 ( Tool Diameter = 0.125 Length = 2.0 )
N043 G20 T2 M6
N044 G54
N045 S10000 M3
N046 G90G0X0.4375Y0.0002
N047 G43Z0.25H2
N048 M8
N049 G0
N050 G1Z-0. F97.5
N051 G02Z-0.125I-0.4375J-0.0002 F195.
N052 G02Z-0.25I-0.4375J-0.0002
N053 G02X-0.4375Y-0.0002I-0.4375J-0.0002
N054 G02X0.4375Y0.0002I0.4375J0.0002
N055 G0Z0.25
N056 (Deep Drill)
N057 ( Tool Diameter = 0.25 Length = 3.0 )
N058 G20 T3 M6
N059 G54
N060 S190 M3
N061 G90G0X0.75Y-0.75
N062 G43Z0.25H3
N063 M7
N064 G0
N065 G83X0.75Y-0.75Z-0.3222R0.1Q0.1F10.
N066X-0.75Y-0.75
N067X-0.75Y0.75
N068X0.75Y0.75
N069 G80
N070 G0Z0.25
N071 M30
%
```


The second half of the complete G-Code file.

## 4.4 The 2½ Axis Profiling Operation G-Code

This toolpath strategy has [Compensation](#) enabled, a [Climb Cut Direction](#) and linear entry and exit motions. It also has [External Corner Type](#) set to [Loop](#) from the [Cornering Parameters](#) tab. With the [Fit Arcs](#) option enabled from the [Advanced Cut Parameters](#) tab, the four corner loops are automatically converted to arc motions, shown in dark blue in the illustration below.







The 2½ Axis Profiling Operation and G-Code

N006 (2 1/2 Axis Profiling (Outer))	General
N007 ( Tool Diameter = 0.25 Length = 2.0 )	Start/End
N008 G20 T1 M6	Tool Change
N009 S10000 M3	Setup
N010 G90G0X-1.2533Y-0.3524	Spindle
N011 G43Z0.25H1	Feed Rate
N012 M8	Motion
N013 G0	Circle
N014 G1Z-0.25 F97.5	Helical/Spiral
N015 G41 G1 X-1.2533 Y-0.3524 D1 F146.25	Multi Axis Motion
N016 G1X-1.1678Y-0.1175	Cutter Compensation
N017 G1X-1.125Y0.	Cut Motion Start/End
N018 G1Y1. F195.	Cycles
N019 G1Y1.25	Misc
N020 G17	Variables
N021 G03X-1.25Y1.125I-0.125J0.	
N022 G1X-1.	
N023 G1X1.	
N024 G1X1.25	
N025 G03X1.125Y1.25I0.J0.125	
N026 G1Y1.	
N027 G1Y-1.	
N028 G1Y-1.25	
N029 G03X1.25Y-1.125I0.125J0.	
N030 G1X1.	
N031 G1X-1.	
N032 G1X-1.25	
N033 G03X-1.125Y-1.25I0.J-0.125	
N034 G1Y-1.	
N035 G1Y0.	
N036 G1Y0.1	
N037 G1X-1.2105Y0.3349 F243.75	
N038 G40	
N039 G1X-1.296Y0.5698 F292.5	
N040 G0Z0.25	

The portion of the G-Code sample file created for the 2½ Axis Profiling operation is shown.

The following PPG sections affect how the G-Code for this operation is defined:

[General](#)

[Tool Change](#)

[Misc](#)

[Motion](#)

[Cutter Compensation](#)[Cycles](#)

## 4.5 The 2½ Axis Hole Profiling Operation G-Code

This toolpath strategy is defined by a helical motion. Because [Hole Depth](#) is set to 0.25 and the [Helix Pitch Height](#) is set to 0.125, a total of two helical motions are required. The options to [Create full \(360 degree\) helixes only](#) and [Output each helix individually](#) are enabled. The [Cut Direction](#) is set to [Conventional \(Up Cutting\)](#).


The screenshot shows the 'Hole Profiling' dialog box with the following settings:

- Control Geometry:** Clearance Plane
- Tool:** (empty)
- Feeds & Speeds:** Entry/Exit, Sorting
- Cut Parameters:**
  - Global Parameters:** Tolerance (t) = 0.001
  - Location of Cut Geometry:** ☒ At Top, ☐ At Bottom, ☐ Pick Top (0)
  - Hole Depth (H):** 0.25, ☐ Determine using 3D model
  - Hole Diameter (D):** For points: 1, ☒ For arcs, use arc diameter
  - Cut Direction:** ☐ Climb (Down Cutting), ☒ Conventional (Up Cutting)
  - Helix Pitch:** ☒ Height (h) = 0.125, ☐ Angle (A) = 10
  - ☒ Create full (360 degree) helixes only
  - ☒ Output each helix individually

A 3D diagram on the right illustrates the hole profiling operation, showing a cylindrical hole with diameter D, depth H, and a helical path with pitch height h and angle A.

Buttons at the bottom: Generate, Cancel, Save, Help.

The 2½ Axis Hole Profiling Operation Cut Parameters



The 2½ Axis Hole Profiling toolpath has a Clockwise spindle direction and a Convention (Up Cutting) Cut Direction. Two full 360 degree helical motions are created. At the bottom of the hole profile two 180 degree arc motions are defined.

N041 (Hole Profiling)	General
N042 ( Tool Diameter = 0.125 Length = 2.0 )	Start/End
N043 G20 T2 M6	Tool Change
N044 G54	Setup
N045 S10000 M3	Spindle
N046 G90G0X0.4375Y0.0002	Feed Rate
N047 G43Z0.25H2	Motion
N048 M8	Circle
N049 G0	Helical/Spiral
N050 G1Z-0. F97.5	Multi Axis Motion
N051 G02Z-0.125I-0.4375J-0.0002 F195.	Cutter Compensation
N052 G02Z-0.25I-0.4375J-0.0002	Cut Motion Start/End
N053 G02X-0.4375Y-0.0002I-0.4375J-0.0002	Cycles
N054 G02X0.4375Y0.0002I0.4375J0.0002	Misc
N055 G0Z0.25	Variables

The portion of the G-Code sample file created for the 2½ Axis Hole Profiling operation is shown.

The following PPG sections affect how the G-Code for this operation is defined:

[General](#)

[Tool Change](#)

[Misc](#)

[Motion](#)


[Helical/Spiral](#)

[Circle](#)


[Cycles](#)

## 4.6 The Deep Drilling Operation G-Code

This toolpath strategy is defined by a **Drill** cycle. The **Hole Depth** is set to 0.25. The **Drill Type** is set to **Deep Drill**. This enables the **Step Increment** option which is set to 0.1 creating three drill increments for each of the four holes (i.e., the drill will peck down three times to complete one hole). We have also enabled **Add Tool tip to Drill Depth**. This ensures a thru hole by taking into account the tip angle of the tool when calculating the drill depth. **Minimum Distance Sort** is also selected from the **Sorting** tab determining the fastest drill sequence.



The Cut Parameters tab for the Drilling operation.



The Drill toolpath is set to Deep Drill (G83) and has an Approach Distance of 0.1 and a Step Increment of 0.1. Add Tool tip to Drill Depth makes the total drill depth 0.32 (shown on the G83 line) when the stock is only 0.25.

N056 (Deep Drill)	General
N057 ( Tool Diameter = 0.25 Length = 3.0 )	Start/End
N058 G20 T3 M6	Tool Change
N059 G54	Setup
N060 S190 M3	Spindle
N061 G90G0X0.75Y-0.75	Feed Rate
N062 G43Z0.25H3	Motion
N063 M7	Circle
N064 G0	Helical/Spiral
N065 G83X0.75Y-0.75Z-0.3222R0.1Q0.1F10.	Multi Axis Motion
N066X-0.75Y-0.75	Cutter Compensation
N067X-0.75Y0.75	Cut Motion Start/End
N068X0.75Y0.75	Cycles
N069 G80	Misc
N070 G0Z0.25	Variables
N071 M30	
%	

The portion of the G-Code sample file created for the Drilling operation is shown.

The following PPG sections affect how the G-Code for this operation is defined:

[General](#)

[Tool Change](#)

[Misc](#)

[Motion](#)


[Cycles](#)

## The Post-Processor Generator Dialog

The topics below show you how our sample post ([haas-blog.spm](#)) is defined within the [PPG](#). We began with the standard *haas.spm* post definition file and added a few changes and customizations. ALL of the customizations were performed using the [PPG](#) dialog. The sample G-Code file was not edited or formatted manually except for adding our color-codes. We added the colors to make it easier for you to follow this article and better understand how the different [PPG](#) sections work together to produce the G-Code.

### 5.1 PPG > General

The [General](#) section of the [PPG](#) includes options that affect the entire G-Code file. [Modes](#) are set, [Units](#) are defined, [Comments](#) are enabled, [Sequence #s](#) are enabled and defined, along with other formatting options. The [Modal Output](#) check boxes determine if values are repeated on every line or only when the value changes.



**General**

This is the color code for the [General](#) section.



<b>File Control</b> Output File Extension <input type="text" value="nc"/> File Start Reading Char <input type="text" value="%"/> File Stop Reading Char <input type="text" value="%"/>	<b>Mode</b> <input checked="" type="radio"/> Absolute Code <input type="text" value="G90"/> <input type="radio"/> Incremental Code <input type="text" value="G91"/>	<b>Comments</b> <input checked="" type="checkbox"/> Output Comment Comment Start Char <input type="text" value="("/> Comment End Char <input type="text" value=")"/> <input type="checkbox"/> Output sequence number
<b>Sequence #s</b> <input checked="" type="checkbox"/> Use Sequence #s Prefix Letter <input type="text" value="N"/> Increment <input type="text" value="1"/> Start value <input type="text" value="1"/> <input checked="" type="checkbox"/> Show Leading Zeros Number of Digits <input type="text" value="4"/>	<b>Units</b> <input checked="" type="radio"/> Inch Code <input type="text" value="G20"/> <input type="radio"/> Metric Code <input type="text" value="G21"/>	<b>Block Format</b> Delimiter <input type="radio"/> None <input checked="" type="radio"/> Space <input type="radio"/> Tabs <input type="radio"/> User Defined <input type="text" value=","/> End of Block Character <input type="text"/> <input type="checkbox"/> Always output + sign <input checked="" type="checkbox"/> Show Leading Zeros
<b>Modal Output</b> <input type="checkbox"/> GCode <input checked="" type="checkbox"/> Feedrate <input checked="" type="checkbox"/> Coordinate <input checked="" type="checkbox"/> Spindle speed		

The General section of the Post-Processor Generator (PPG) dialog for our haas-blog.spm post definition file.

Resulting G-Code Sample
<pre> ( ENDOF TOOL LIST ) N003 (Setup 1) N004 (Work Zero) N005 G54 N006 (2 1/2 Axis Profiling (Outer)) N007 ( Tool Diameter = 0.25 Length = 2.0 )           </pre>

## 5.2 PPG > Start/End

The [Start/End](#) section of the [PPG](#) allows you to define how the start and end sections of the G-Code file are formatted and what codes are included in these sections. The [Start Up](#) section typically includes codes to make sure various machine functions are turned off. We have customized it to add the stock size.



This is the color code for the [Start/End](#) section.

The tables below lists [Start Up Code](#) and the [End Code](#) along with the variables used and how those variables were defined. Note that variables are written within brackets [ ] and comments are written within parentheses ( ).



The Start/End section of the Post-Processor Generator (PPG) dialog for our `haas-blog.spm` post definition file.

Start Up Code	
[START_CHAR] O[PARTNUM] [SEQ_PRECHAR][SEQNUM][DELIMITER]G40[DELIMITER]G49[DELIMITER]G80 [SEQ_PRECHAR][SEQNUM][DELIMITER]([ STOCK SIZE: X[STOCK_LENGTH_X] Y[STOCK_LENGTH_Y] Z[STOCK_LENGTH_Z] )	
Variable	Derived From
[START_CHAR]	<a href="#">File Start Reading Character</a> from the <a href="#">General</a> section of the <a href="#">PPG</a> .
[DELIMITER]	<a href="#">Delimiter</a> type from the <a href="#">General</a> section of the <a href="#">PPG</a> . This is set to insert a space between

	values just to make it easier to read the posted output file.
[PARTNUM]	Right-click > <a href="#">Properties</a> on the first <a href="#">Machining Operation (Mop)</a> under the first <a href="#">Setup</a> in the <a href="#">Machining Job</a> .
[SEQ_PRECHAR]	<a href="#">Prefix Letter</a> from the <a href="#">General</a> section of the PPG.
[SEQNUM]	Use <a href="#">Sequence #s</a> from the <a href="#">General</a> section of the PPG.
[STOCK_LENGTH_X]	MecSoft CAM > <a href="#">MILL</a> > <a href="#">Machining Job</a> > <a href="#">Stock</a> > <a href="#">Length (L)</a>
[STOCK_LENGTH_Y]	MecSoft CAM > <a href="#">MILL</a> > <a href="#">Machining Job</a> > <a href="#">Stock</a> > <a href="#">Width (W)</a>
[STOCK_LENGTH_Z]	MecSoft CAM > <a href="#">MILL</a> > <a href="#">Machining Job</a> > <a href="#">Stock</a> > <a href="#">Height (H)</a>
ISO Codes	Function
G40	Cutter Compensation Off
G49	Tool Length Compensation Off
G80	Canned Cycle Off
Resulting G-Code Sample	
<pre>% O1234 N001 G40 G49 G80 N002 ( STOCK SIZE: X2.125 Y2.125 Z0.25 ) ( BEGIN TOOL LIST )</pre>	
End Code	
<pre>[SEQ_PRECHAR][SEQNUM][DELIMITER]M30 [STOP_CHAR]</pre>	
Variable	Derived From
[DELIMITER]	<a href="#">Delimiter</a> type from the <a href="#">General</a> section of the PPG.

[SEQ_PRECHAR]	Prefix Letter from the <a href="#">General</a> section of the PPG.
[SEQNUM]	Use Sequence #s from the <a href="#">General</a> section of the PPG.
[STOP_CHAR]	File Stop Reading Character from the <a href="#">General</a> section of the PPG.
ISO Codes	Function
M30	End of Program
Resulting G-Code Sample	
<pre> N069 G80 N070 G0Z0.25 N071 M30 %</pre>	

### 5.3 PPG > Tool Change

The [Tool Change](#) section of the [PPG](#) allows you to define the [First Tool Load Macro](#) and the [Tool Change Macro](#) for subsequent tool changes. These macros define all of the information your CNC controller needs to load and change cutting tools and move the tool into position.



This is the color code for the [Tool Change](#) section.

This section is ignored if your CNC machine does not have an automatic tool changer. The reason these are called Macros is because they use nested variables. For example [\[SPINDLE\\_BLK\]](#) is the result of the [Spindle Block Format](#) code defined in the [Spindle](#) section of the [PPG](#).

First you will notice that [Output tool list as comments at start of program](#) is checked. Because [Comments](#) are enabled in the [General](#) section of the [PPG](#), the following comments are listed at the top of the G-Code file:

N002 ( STOCK SIZE: X2.125 Y2.125 Z0.25 )

( BEGIN TOOL LIST )

( TOOL 1 - FlatMill:0.25 - DESC: 0.2500 DIA, 2 FLUTE, CARBIDE MAT )

( TOOL 2 - FlatMill:0.125 - DESC: 0.1250 DIA, 2 FLUTE, CARBIDE MAT )

( TOOL 3 - Drill: 1/4" - DESC: 0.2500 DIA, 2 FLUTE, CARBIDE MAT )

( ENDOF TOOL LIST )

N003 (Setup 1)

Output tool list as comments

Now onto the macros.

☐ Use 2 digit format for Tool number and registers ☒ Output tool list as comments at start of program

First Load Tool Macro

```
(SEQ_PRECHAR)[SEQNUM][DELIMITER]( Tool Diameter = [TOOL_DIA] Length = [TOOL_LENGTH] )
(SEQ_PRECHAR)[SEQNUM][DELIMITER][OUTPUT_UNITS_CODE][DELIMITER]T[TOOL_NUM][DELIMITER]M6
(SEQ_PRECHAR)[SEQNUM][DELIMITER][SPINDLE_BLK]
(SEQ_PRECHAR)[SEQNUM][DELIMITER][OUTPUT_MODE_CODE][G_CODE]X[NEXT_NONMDL_X]Y[NEXT_NONMDL_Y]
(SEQ_PRECHAR)[SEQNUM][DELIMITER]G43Z[NEXT_NONMDL_Z]H[TOOL_ADJST_REG]
```

Tool Change Macro

```
(SEQ_PRECHAR)[SEQNUM][DELIMITER]( Tool Diameter = [TOOL_DIA] Length = [TOOL_LENGTH] )
(SEQ_PRECHAR)[SEQNUM][DELIMITER][OUTPUT_UNITS_CODE][DELIMITER]T[TOOL_NUM][DELIMITER]M6
(SEQ_PRECHAR)[SEQNUM][DELIMITER][WORK_OFFSET_PREFIX][WORK_OFFSET_NUM]
(SEQ_PRECHAR)[SEQNUM][DELIMITER][SPINDLE_BLK]
(SEQ_PRECHAR)[SEQNUM][DELIMITER][OUTPUT_MODE_CODE][G_CODE]X[NEXT_NONMDL_X]Y[NEXT_NONMDL_Y]
(SEQ_PRECHAR)[SEQNUM][DELIMITER]G43Z[NEXT_NONMDL_Z]H[TOOL_ADJST_REG]
```

The Tool Change section of the Post-Processor Generator (PPG) dialog for our haas-blog.spm post definition file.

First Load Tool Macro	
<pre>(SEQ_PRECHAR)[SEQNUM][DELIMITER]( Tool Diameter = [TOOL_DIA] Length = [TOOL_LENGTH] ) (SEQ_PRECHAR)[SEQNUM][DELIMITER][OUTPUT_UNITS_CODE][DELIMITER]T[TOOL_NUM][DELIMITER]M6 (SEQ_PRECHAR)[SEQNUM][DELIMITER][SPINDLE_BLK] (SEQ_PRECHAR)[SEQNUM][DELIMITER][OUTPUT_MODE_CODE][G_CODE]X[NEXT_NONMDL_X]Y[NEXT_NONMDL_Y] (SEQ_PRECHAR)[SEQNUM][DELIMITER]G43Z[NEXT_NONMDL_Z]H[TOOL_ADJST_REG]</pre>	
Variable	Derived From
[TOOL_DIA]	MecSoft CAM > <a href="#">Tools</a> > <a href="#">Create/Select Tool</a> > <a href="#">Tool Dia.</a>
[TOOL_LENGTH]	MecSoft CAM > <a href="#">Tools</a> > <a href="#">Create/Select Tool</a> > <a href="#">Tool Length.</a>

[OUTPUT_UNITS_CODE]	Units Code from the <a href="#">General</a> section of the PPG.
[TOOL_NUM]	MecSoft CAM > <a href="#">Tools</a> > <a href="#">Create/Select Tool</a> > <a href="#">Tool Number</a> .
[SPINDLE_BLK]	<a href="#">Spindle Block</a> from the <a href="#">Spindle</a> section of the PPG.
[OUTPUT_MODE_CODE]	Mode Code from the <a href="#">Spindle</a> section of the PPG.
[G_CODE]	This will be either G0 or G1 depending on the Transfer feed rate value on the <a href="#">Feeds &amp; Speeds</a> tab of the first <a href="#">Mop</a> . G0=Rapid, G1=Feed Rate
[NEXT_NONMDL_X]	The next X coordinate if different than the last (non modal). Because <a href="#">Coordinate</a> is checked under <a href="#">Model Output</a> in the <a href="#">General</a> section, coordinates are only displayed if it is different than the last coordinate value.
[NEXT_NONMDL_Y]	The next Y coordinate if different than the last (non modal).
[NEXT_NONMDL_Z]	The next Z coordinate if different than the last (non modal).
[TOOL_ADJST_REG]	MecSoft CAM > <a href="#">Tools</a> > <a href="#">Create/Select Tool</a> dialog > <a href="#">Adjust Register</a> . Should be the same as <a href="#">Tool Number</a> .
ISO Codes	Function
M6	Tool Change
G43	Apply Tool Length Compensation
<b>Resulting G-Code Sample</b>	
N006 (2 1/2 Axis Profiling (Outer)) N007 ( Tool Diameter = 0.25 Length = 2.0 ) N008 G20 T1 M6 N009 S10000 M3 N010 G90G0X-1.2533Y-0.3524 N011 G43Z0.25H1 N012 M8	

### Tool Change Macro

<pre> [SEQ_PRECHAR][SEQNUM][DELIMITER][ Tool Diameter = [TOOL_DIA] Length = [TOOL_LENGTH] ) [SEQ_PRECHAR][SEQNUM][DELIMITER][OUTPUT_UNITS_CODE][DELIMITER]T[TOOL_NUM][DELIMITER]M6 [SEQ_PRECHAR][SEQNUM][DELIMITER][WORK_OFFSET_PREFIX][WORK_OFFSET_NUM] [SEQ_PRECHAR][SEQNUM][DELIMITER][SPINDLE_BLK] [SEQ_PRECHAR][SEQNUM][DELIMITER][OUTPUT_MODE_CODE][G_CODE]X[NEXT_NONMDL_X]Y[NEXT_NONMDL_Y] [SEQ_PRECHAR][SEQNUM][DELIMITER]G43Z[NEXT_NONMDL_Z]H[TOOL_ADJUST_REG] </pre>	
Variable	Derived From
[TOOL_DIA]	MecSoft CAM > <a href="#">Tools</a> > <a href="#">Create/Select Tool</a> > <a href="#">Tool Dia.</a>
[TOOL_LENGTH]	MecSoft CAM > <a href="#">Tools</a> > <a href="#">Create/Select Tool</a> > <a href="#">Tool Length.</a>
[OUTPUT_UNITS_CODE]	<a href="#">Units Code</a> from the <a href="#">General</a> section of the <a href="#">PPG</a> .
[TOOL_NUM]	MecSoft CAM > <a href="#">Tools</a> > <a href="#">Create/Select Tool</a> > <a href="#">Tool Number.</a>
[WORK_OFFSET_PREFIX]	<a href="#">Work Offset Code</a> from the <a href="#">Misc</a> section of the <a href="#">PPG</a> .
[WORK_OFFSET_NUM]	MecSoft CAM > <a href="#">Machining Job</a> > <a href="#">Work Zero</a> > <a href="#">Work Offset Register Number.</a>
[SPINDLE_BLK]	<a href="#">Spindle Block</a> from the <a href="#">Spindle</a> section of the <a href="#">PPG</a> .
[OUTPUT_MODE_CODE]	<a href="#">Mode Code</a> from the <a href="#">Spindle</a> section of the <a href="#">PPG</a> .
[G_CODE]	This will be either G0 or G1 depending on the Transfer feed rate value on the <a href="#">Feeds &amp; Speeds</a> tab of the first <a href="#">Mop</a> . G0=Rapid, G1=Feed Rate
[NEXT_NONMDL_X]	The next X coordinate if different than the last (non modal). Because <a href="#">Coordinate</a> is checked under <a href="#">Model Output</a> in the <a href="#">General</a> section, coordinates are only displayed if it is different than the last coordinate value.
[NEXT_NONMDL_Y]	The next Y coordinate if different than the last (non modal).
[NEXT_NONMDL_Z]	The next Z coordinate if different than the last (non modal).
[TOOL_ADJUST_REG]	MecSoft CAM > <a href="#">Tools</a> > <a href="#">Create/Select Tool</a> dialog > <a href="#">Adjust Register</a> . Should be the same as <a href="#">Tool Number</a> .
ISO Codes	Function
M6	Tool Change
G43	Apply Tool Length Compensation
Resulting G-Code Sample	

```

N041 (Hole Profiling)
N042 ( Tool Diameter = 0.125 Length = 2.0 )
N043 G20 T2 M6
N044 G54
N045 S10000 M3
N046 G90G0X0.4375Y0.0002
N047 G43Z0.25H2
N048 M8

```

## 5.4 PPG > Setup

The [Setup](#) section of the [PPG](#) is only used if your [Machine](#) definition is set to [4 Axis](#) or [5 Axis](#) (MecSoft CAM > [Machining Job](#) > [Machine](#)). It is used to output the rotation axis and angles for the setup. This will be covered in a future guide.

Work Offset

Setup 0 (Coordinate System Change) Macro:

```
[LINEAR][NEXT_X][NEXT_Y][NEXT_Z][ROTATION_AXIS][ROTATION_DIR][ANGLE][FEEDRATE_CODE][ROTATION_FEEDVALUE]
```

Setup 1 (Rotate Table) Macro:

```
[ROTATION_AXIS][ROTATION_DIR][ANGLE][FEEDRATE_CODE][ROTATION_FEEDVALUE]
```

Default

The Setup section of the Post-Processor Generator (PPG) dialog for our haas-blog.spm post definition file.



## 5.5 PPG > Spindle

The **Spindle** section of the **PPG** defines the **Spindle Block** variable `[SPINDLE_BLK]`. It is also used to set the **High** and **Low** values for the **Spindle RPM**. These values will not be exceeded regardless of the tool or toolpath parameters. This section also defines the **Spindle Direction** and other spindle related values.

**Spindle**

This is the color code for the **Spindle** section.

The **Spindle** section of the Post-Processor Generator (PPG) dialog for our `haas-blog.spm` post definition file.

Spindle Block Format	
S[SPINDLE_SPD][DELIMITER][SPINDLE_ARC]	
Variable	Derived From
[SPINDLE_SPD]	MecSoft CAM > Tools > Create/Select Tool dialog > Feeds & Speeds or Mop > Feeds & Speeds > Spindle Speed

[SPINDLE_ARC]	MecSoft CAM > Tools > Create/Select Tool dialog > Feeds & Speeds or Mop > Feeds & Speeds > Direction
ISO Codes	Function
M3	Spindle On, Clockwise rotation
M4	Spindle On, Counter Clockwise rotation
Resulting G-Code Sample	
N006 (2 1/2 Axis Profiling (Outer)) N007 ( Tool Diameter = 0.25 Length = 2.0 ) N008 G20 T1 M6 N009 S10000 M3 N010 G90G0X-1.2533Y-0.3524 N011 G43Z0.25H1 N012 M8	

## 5.6 PPG > Feed Rate

The [Feed Rate](#) section of the [PPG](#) defines the block format for Feed Rate. The [Feed Rate Block](#) is inserted only when the feed rate changes if [Feedrate](#) is checked under [Modal Output](#) in the [General](#) section of the [PPG](#). You can also set the [High](#) and [Low](#) values for [Feedrate](#) here as well as other parameters related to feed rate.



Feed  
Rate

This is the color code for the [Feed Rate](#) section.

Block Format

Feed Rate Code:

Feed Rate Modes

Units/Min Code:  Units/Rev Code:

Inverse Time Feed Rate

☐ Output inverse time feedrate for 4 & 5 Axis motions

On Code:  Off Code:

Block Format

Sample Output

Feed Rate Value

High Value:  Scale Factor:  Z Feed Rate Scale Factor:

Low Value:  # of Decimal Places:  Show Trailing Zeros: ☐

Angular Feedrate Value

Scale Factor:  # of Decimal Places:  Show Trailing Zeros: ☐

The Feed Rate section of the Post-Processor Generator (PPG) dialog for our haas-blog.spm post definition file.

Feed Rate Block Format	
F[FEEDRATE]	
Variable	Derived From
[FEEDRATE]	MecSoft CAM > <a href="#">Tools</a> > <a href="#">Create/Select Tool</a> dialog > Feeds & Speeds or <a href="#">Mop</a> > <a href="#">Feeds &amp; Speeds</a>
Resulting G-Code Sample	
<pre> N049 G0 N050 G1Z-0. F97.5 N051 G0Z-0.125I-0.4375J-0.0002 F195. N052 G0Z-0.25I-0.4375J-0.0002 </pre>	

5.7 PPG > Motion

The **Motion** section of the **PPG** defines the **Linear Motion** and **Rapid Motion Block** Format. Anytime a linear or rapid motion is defined it is output in this format. This section also allows you to control other aspects of motion coordinates including X, Y and Z Scale Factors, # of Decimal Places and more.



This is the color code for the **Motion** section.

Linear Motion Block Format

G Code

G1

Block Format

[G\_CODE][NEXT\_X][NEXT\_Y][NEXT\_Z]

Sample Output

G1X0.0Y0.0Z0.0

Output cut motion start macro before plunge motion

☐

Rapid Motion Block Format

G Code

G0

Block Format

[G\_CODE][NEXT\_Z]  
[NEXT\_X][NEXT\_Y]

Sample Output

G0Z0.0  
X0.0Y0.0

Motion Coordinates

Scale Factor for X

1

Scale Factor for Y

1

Scale Factor for Z

1

Show Trailing Zeros


☐

# of Decimal Places

4

The Motion section of the Post-Processor Generator (PPG) dialog for our haas-blog.spm post definition file.

Linear Motion Block Format
[G_CODE][NEXT_X][NEXT_Y][NEXT_Z]
Rapid Motion Block Format

[G_CODE][NEXT_Z] [NEXT_X][NEXT_Y]	
Variable	Derived From
[G_CODE]	Will be G1 for a Linear motion or G0 for a Rapid motion
[NEXT_Z]	The next Z coordinate value
[NEXT_X]	The next X coordinate value
[NEXT_Y]	The next Y coordinate value
<b>Resulting G-Code Sample</b>	
	

## 5.8 PPG > Circle

The [Circle](#) section of the [PPG](#) defines all arc motions. At the top you see the G-Code and [Plane Code](#) sections. This is followed by the [Output Format](#) and [Arc Center \(I, J, K\)](#) sections. The options in these two sections define how the arc code is formatted and specifically how the arc center is calculated.


### Circle

This is the color code for the [Circle](#) section.

Be sure to read the resulting G-Code sample illustration below to understand how the arc motions are defined for our sample part.

What is needed to output Arc Motions:

- Your CNC controller must be able to read G02 and G03 arc motions.
- In MecSoft CAM go to [MILL > Preferences > Machining](#) and uncheck [Output arcs as linear segments](#) and also uncheck [Output helix motions as linear segments](#). If these boxes are checked, arcs are converted to linear motions.



MILL &gt; CAM Preferences &gt; Machining dialog

- In the [Advanced Cut Parameters](#) tab for the [Mop](#), check the box for [Perform Arc Fitting](#) and enter a value for [Fitting tolerance \(t\)](#). As a rule, this value should be 2 times the value you entered for [Tolerance](#) on the [Cut Parameters](#) tab. If you need a tighter tolerance, adjust these two values together.



Tolerance value on the Cut Parameters tab for 2 ½ Axis Profiling



Perform Arc Fitting on the Advanced Cut Parameters tab for 2½ Axis Profiling

<b>G Code</b> Clockwise Arc Code <input type="text" value="G02"/> C-clockwise Arc Code <input type="text" value="G03"/>		<b>Plane Code</b> XY <input type="text" value="G17"/> ZX <input type="text" value="G18"/> YZ <input type="text" value="G19"/>	
<b>Output Format</b> <input type="radio"/> I, J, K and Radius <input checked="" type="radio"/> I, J, K only <input type="radio"/> Radius only <input type="checkbox"/> Output values only when different <input type="checkbox"/> Use -R for CW Arcs		<b>Arc Center (I, J, K)</b> <input type="radio"/> Absolute <input type="radio"/> Vector from Center to Start <input checked="" type="radio"/> Vector from Start to Center <input type="radio"/> Unsigned Vector from Start to Center	
<b>Block Format</b> Select Plane Plane XY Plane ZX  [CIR_PLANE] [G_CODE][NEXT_X][NEXT_Y][NEXT_I][NEXT_J]  Sample Output {G17/G18/G19} {G02/G03}X0.0Y0.0I0J0			
<input type="checkbox"/> Limit Arcs to Angle <input type="text" value="180"/>		<input type="button" value="Default"/>	

The Circle section of the Post-Processor Generator (PPG) dialog for our haas-blog.spm post definition file.

Circle Block Format	
[CIR_PLANE] [G_CODE][NEXT_X][NEXT_Y][NEXT_I][NEXT_J]	
Variable	Derived From
[CIR_PLANE]	The <a href="#">Plane Code</a> defined in this section of the <a href="#">PPG</a> (G17=XY Plane, G18=ZX Plane and G19=YZ Plane)
[G_CODE]	The <a href="#">G Code</a> defined in this section of the <a href="#">PPG</a> (G02 for a clockwise arc and G03 for a counter clockwise arc)
[NEXT_X]	The X coordinate value for the arc end point
[NEXT_Y]	The Y coordinate value for the arc end point
[NEXT_Z]	The Z coordinate value for the arc end point
[NEXT_I]	The X coordinate value for the arc center point
[NEXT_J]	The Y coordinate value for the arc center point
[NEXT_K]	The Z coordinate value for the arc center point

Resulting G-Code Sample		
	Start X	
N017	G1X-1.125Y0.	
N018	G1Y1. F195.	
N019	G1Y1.25	Start Y
N020	G17	XY Plane
N021	G03X-1.25Y1.125I-0.125J0.	
	Dir	End XY Center IJ

How arc motions are defined for our sample.

**Notes:**

1. I, J and K represent the arc center as an offset distance from the arc start. This is because in the PPG, [Arc Center \( I, J, K \)](#) section we have select [Vector from Center to Start](#). If you want the arc center posted in absolute coordinates, select the [Absolute](#) option.
2. Because the plane of the arc is XY, no Z or K values are shown for the arc start and end.
3. The arc start is located on line N017 because it is the end point of the last linear motion.
4. The red boxes are our added annotations and are not part of the G-Code sample.

## 5.9 PPG > Helical/Spiral

The [Helical/Spiral](#) section of the [PPG](#) defines how all helical and spiral motions are defined. The only difference between an arc and a helix is that a helix has a Z value (i.e., pitch). In fact, a helix is defined using the Arc G-Code with the added Z value. We strongly recommended that you first read the [PPG > Circle](#) section above to understand how arcs are defined before continuing.



## Helical Spiral

This is the color code for the [Helical/Spiral](#) section.

Select Interpolation Type

Helical Interpolation

Spiral Interpolation

G Code

Clockwise Arc Code

C-clockwise Arc Code

Block Format

Select Plane

Plane XY

Plane ZX

Plane YZ

[CIR\_PLANE]  
[G\_CODE][NEXT\_X][NEXT\_Y][NEXT\_Z][NEXT\_I][NEXT\_J]

Default

Sample Output

{G17/G18/G19}  
{G02/G03}X0.0Y0.0Z0.0I0J0

The Helical/Spiral section of the Post-Processor Generator (PPG) dialog for our haas-blog.spm post definition file.

### Helical/Spiral Block Format

[CIR\_PLANE]  
[G\_CODE][NEXT\_X][NEXT\_Y][NEXT\_Z][NEXT\_I][NEXT\_J]

Variable	Derived From
[CIR_PLANE]	The <a href="#">Plane Code</a> defined in this section of the PPG (G17=XY Plane, G18=ZX Plane and G19=YZ Plane)
[G_CODE]	The G Code defined in this section of the PPG (G02 for a clockwise arc and G03 for a counter clockwise arc)
[NEXT_X]	The X coordinate value for the helix end point
[NEXT_Y]	The Y coordinate value for the helix end point

[NEXT_Z]	The Z coordinate value for the helix end point
[NEXT_I]	The X coordinate value for the helix center point
[NEXT_J]	The Y coordinate value for the helix center point
[NEXT_K]	The Z coordinate value for the arc center point
<b>Resulting G-Code Sample</b>	
N046 G90G0X0.4375Y0.0002	← X, Y Start of Helix
N047 G43Z0.25H2	
N048 M8	
N049 G0	
N050 G1Z-0. F97.5	← Z Start of Helix
N051 G02Z-0.125I-0.4375J-0.0002 F195.	← First Full Helix
N052 G02Z-0.25I-0.4375J-0.0002	← Second Full Helix
N053 G02X-0.4375Y-0.0002I-0.4375J-0.0002	← First Arc Clean up
N054 G02X0.4375Y0.0002I0.4375J0.0002	← Second Arc Clean up
Notes:	
<ol style="list-style-type: none"> <li>1. Notice that the X, Y start of the helix is one line N046 and the Z start of the helix is on line N050.</li> <li>2. Lines N051 and N052 are the two helical motions. Notice that each includes a Z coordinate value.</li> <li>3. Line N051 create the first full helix starting a Z0 and ending at Z0.125.</li> <li>4. Line N052 create the second full helix starting a Z0.125 and ending at Z0.25.</li> <li>5. Lines N053 and N054 are the two arc motions located at the base of the hole. Together they form a complete circle which serves as a clean up pass.</li> </ol>	

## 5.10 PPG > Multi Axis Motion

The [Multi Axis Motion](#) section of the PPG is only used if your [Machine](#) definition is set to [4 Axis](#) or [5 Axis](#) (MecSoft CAM > [Machining Job](#) > [Machine](#)). It is used to define the [Rotation Axis Code](#), [Rotation Direction Code](#), [Angle Value](#), and the [Motion Block](#). This will be covered in a future blog post.

**Block Format**

**Rotation Axis Code**

Primary Axis  Secondary Axis  Tertiary Axis

**Rotation Direction Code**

Clockwise Rotation  Counter Clockwise Rotation  ☒ Ignore in continuous rotation toolpaths

**Angle Value**

Scale Factor  # Decimal Places  Trailing Zeros ☐

**Motion Block**

Block Format

[LINEAR][NEXT\_X][NEXT\_Y][NEXT\_Z][ROTATION\_AXIS][ROTATION\_DIR][ANGLE][FEEDRATE\_CODE][ROTATION\_FEEDVALUE]

**Sample Output**

G1X0.0Y0.0Z0.0A-0F0

**Rapid Block**

Block Format

[RAPID][NEXT\_X][NEXT\_Y][NEXT\_Z][ROTATION\_AXIS][ROTATION\_DIR][ANGLE][FEEDRATE\_CODE][ROTATION\_FEEDVALUE]

**Sample Output**

G0X0.0Y0.0Z0.0A-0F0

The Multi Axis Motion section of the Post-Processor Generator (PPG) dialog for our haas-blog.spm post definition file.

## 5.11 PPG > Cutter Compensation


The [Cutter Compensation](#) section of the [PPG](#) is used to provide a way to adjust the toolpath at the machine to compensate for tool size, tool wear, and tool deflection. The dialog provides the block format for Cutter [Compensation Left](#) (G41), [Cutter Compensation Right](#) (G42) and [Cutter Compensation Off](#) (G40). G41 is used for a climb (down cut) direction with a clockwise (right-handed) spindle direction. G42 is used for a conventional (up cut) direction.

**Cutter  
Compensation**


This is the color code for the [Cutter Compensation](#) section.

What is needed to output Cutter Compensation:


1. In the [Cut Parameters](#) tab under [Global Parameters](#) set [Compensation](#) to either [Auto/On](#) or [Control/On](#). In our example, we have it set to [Control/On](#).



2. In the **Cut Parameters** tab set **Cut Direction** to either **Climb** or **Conventional**. Do not set it to **Mixed** as this will disable **Cutter Compensation**. In our example we have it set to **Climb**.
3. Your first cut motion must be linear. In our example, on the **Entry/Exit** tab of the **2 1/2 Axis Profiling Mop**, **Entry Motions** is set to **Lines & Arcs** and the **Engage Motion** is set to **Linear**. Similarly, the **Exit Motions** is set to **Lines & Arcs** and the **Retract Motion** is set to **Linear**.



4. In your tool definition make sure the **Cutcom Register** is set to the same value as the **Tool Number**. **Tool Number**, **Adjust Register** and **Cutcom Register** should all be the same value.



Properties Feeds & Speeds

Material CARBIDE

Cut Material Color

Number of Flutes 2

Tool Number 1

Adjust Register 1

Cutcom Register 1


Axial Offset 0

Coolant Flood

Comments

Properties tab of the Create/Select Tool dialog

5. Make sure to specify the cutter compensation value and the compensation register in your controller.



Cutter Compensation Left

```
[SEQ_PRECHAR][SEQNUM][DELIMITER]G41 [G_CODE] X[NEXT_NONMDL_X] Y[NEXT_NONMDL_Y] D[TOOL_CUTCOM_REG]
```

Cutter Compensation Right

```
[SEQ_PRECHAR][SEQNUM][DELIMITER]G42 [G_CODE] X[NEXT_NONMDL_X] Y[NEXT_NONMDL_Y] D[TOOL_CUTCOM_REG]
```

Cutter Compensation Off


```
[SEQ_PRECHAR][SEQNUM][DELIMITER]G40
```

The Cutter Compensation section of the Post-Processor Generator (PPG) dialog for our haas-blog.spm post definition file.

Cutter Compensation Block Format	
[SEQ_PRECHAR][SEQNUM][DELIMITER]G41 [G_CODE]X[NEXT_NONMDL_X]Y[NEXT_NONMDL_Y]D[TOOL_CUTCOM_REG] [SEQ_PRECHAR][SEQNUM][DELIMITER]G42 [G_CODE]X[NEXT_NONMDL_X]Y[NEXT_NONMDL_Y]D[TOOL_CUTCOM_REG] [SEQ_PRECHAR][SEQNUM][DELIMITER]G40	
Variable	Derived From
[G_CODE]	Will be a G1 linear motion
[TOOL_CUTCOM_REG]	MecSoft CAM > <a href="#">Tools</a> > <a href="#">Create/Select Tool</a> > <a href="#">Properties</a> > <a href="#">Cutcom Register</a> . Should be the same as the <a href="#">Tool Number</a> .
ISO Codes	Function
G41	Cutter Compensation Left
G42	Cutter Compensation Right
G40	Cutter Compensation Off
Resulting G-Code Sample	
N012 M8 N013 G0 N014 G1Z-0.25 F97.5 N015 G41 G1 X-1.2533 Y-0.3524 D1 F146.25 ← Cutter Compensation Left N016 G1X-1.1678Y-0.1175  N037 G1X-1.2105Y0.3349 F243.75 N038 G40 ← Cutter Compensation Off N039 G1X-1.296Y0.5698 F292.5	

## 5.12 PPG > Cut Motion Start/End

The [Cut Motion Start/End](#) section of the [PPG](#) is used for inserting additional code at the start or the end of every cut motion. For example, in the Motion section you can check the box to [Output cut motion start macro before plunge motion](#). If you add codes to the [Start Up Code](#) section below, this option will include it prior to a Z plunge motion.



Cut Motion Start/End

Start Up Code :

End Code :

The Cut Motion Start/End section of the Post-Processor Generator (PPG) dialog for our haas-blog.spm post definition file.

## 5.13 PPG > Cycles


The [Cycles](#) section of the [PPG](#) is used for all canned cycles. These are cycles that your CNC controller is programmed to understand. For example all [Drill](#), [Tap](#) and [Bore Mops](#) are posted out as canned cycles. Other cycles include [User Defined Cycles](#), [Turn Thread Cycles](#) and [Machine Control Cycles](#).



This is the color code for the [Cycles](#) section.

All of these are defined in this [Cycles](#) section of the [PPG](#). We have shown the [Deep Drill](#) cycle dialog below since our part example has a [Drill](#) operation that is set to [Deep Drill](#).

On the left of the [PPG](#) dialog you would expand the [Cycles](#) selection to see all of the supported canned cycles. We are using the [Deep](#) cycle (G83).





Cycle G-Code:

Cycle Code:

```
[SEQ_PRECHAR][SEQNUM][DELIMITER][G_CODE]X[NEXT_NONMDL_X]Y[NEXT_NONMDL_Y]Z[CYCL_Z-DEPTH]R[CYCL_Z+CLEAR]Q[CYCL
```

Optimize Cycle Options

☒ Optimize Cycle Output

Cycle Coordinate Block:

Dwell Options

Scale Factor  # of Decimal Places

Thread First Depth Options

Scale Factor  # of Decimal Places

The Cycles > Deep Drill section of the Post-Processor Generator (PPG) dialog for our haas-blog.spm post definition file.

**Note:** The [Cycle Code](#) shown below is actually one line! We separated it into two lines for presentation purposes. Your G83 cycle code should be all on one line as shown in our part sample below.

Cycle Code	
[SEQ_PRECHAR][SEQNUM][DELIMITER][G_CODE]X[NEXT_NONMDL_X]Y[NEXT_NONMDL_Y]Z[CYCL_Z-DEPTH]R[CYCL_Z+CLEAR]Q[CYCL_INCR]F[CYCL_IPM]	
Variable	Derived From
[G_CODE]	This will be the canned cycle code. Our part sample requires the <a href="#">Deep Drill</a> G83 cycle.
[CYCL_Z-DEPTH]	MecSoft CAM > <a href="#">Drill</a> > <a href="#">Cut Parameters</a> > <a href="#">Drill Depth</a> .
[CYCLE_Z+CLEAR]	MecSoft CAM > <a href="#">Drill</a> > <a href="#">Cut Parameters</a> > <a href="#">Approach Distance</a> .
[CYCLE_INC]	MecSoft CAM > <a href="#">Drill</a> > <a href="#">Cut Parameters</a> > <a href="#">Step Increment</a> .
[CYCLE_IPM]	MecSoft CAM > <a href="#">Drill</a> > <a href="#">Feeds &amp; Speeds</a> > <a href="#">Cut (Cf)</a>
ISO Codes	Function

G83	Deep Drill Cycle
R	Position of the R (retract) plane
Q	Depth of cut for each cutting feed (depth of each peck)
<b>Resulting G-Code Sample</b>	
<pre> N063 M7 N064 G0 N065 G83X0.75Y-0.75Z-0.3222R0.1Q0.1F10. ← Deep Drill (First Hole) N066X-0.75Y-0.75 N067X-0.75Y0.75 ← Optimized Cycle Output (for remaining Holes) N068X0.75Y0.75 N069 G80 ← Cycle Off N070 G0Z0.25 ← Retract to Clearance Plane N071 M30 %</pre>	
<p>Notes:</p> <ol style="list-style-type: none"> <li>1. Line N065 is the first deep drill cycle (G83). On this line Z is the Drill Depth of the hole, R is the Z location of the Approach Distance value and Q is the Step Increment value.</li> <li>2. Lines N066, N067 and N068 are the three remaining holes in the set. With Optimized Cycle Output checked, only the change in X and Y are posted.</li> <li>3. Line N069 cancels the canned cycle (G80).</li> </ol>	

## 5.14 PPG > Misc

The [Misc](#) section of the [PPG](#) is primarily used for [Coolant Codes](#) but also contains the [Work Offset Code](#).



Misc

This is the color code for the [Misc](#) section.

Coolant Codes		Compensation	
Coolant Off	M9	Compensation Off	G40
Coolant Mist	M7	Compensation Right	G42
Coolant Tap	M51	Compensation Left	G41
Coolant On	M51	Compensation Length	G43
Coolant Flood	M8		
Coolant Thru	M50		
		Work (Fixture) Offsets	
		Work Offset Code	G

The Misc section of the Post-Processor Generator (PPG) dialog for our haas-blog.spm post definition file.

## Resulting G-Code Sample

N006 (2 1/2 Axis Profiling (Outer))

N007 ( Tool Diameter = 0.25 Length = 2.0 )

N008 G20 T1 M6

N009 S10000 M3

N010 G90G0X-1.2533Y-0.3524

N011 G43Z0.25H1

N012 M8 ← Coolant = Flood for Tool #1

N013 G0

## Notes:

1. To enable Coolant codes, make sure Coolant is set on the Feeds & Speeds tab of the Mop (MecSoft CAM > Holes > Drill > Feeds & Speeds > Coolant).
2. Even if you have Coolant set for the Tool (MecSoft CAM > Create/Select Tool > Properties > Coolant), it could be overwritten in the Feeds & Speeds tab of the Mop so see note #1 also.

## 5.15 PPG > Variables

The [Variables](#) section of the [PPG](#) lists ALL of the available variables in MecSoft CAM along with the format of the expected values. Variables are used throughout the [PPG](#) and affect the format and output of the entire sample G-Code file. We have color-coded this section but instead have listed each variable used in each [PPG](#) section that affects the sample G-Code file.

Variable Name	Value
[ABS_ANGLE]	0
[ABS_ANGLE_SECONDARY]	
[ANGLE]	0
[ANGLE_SECONDARY]	0
[APPROACH_FEED]	0.0
[CENTER_X]	0
[CENTER_Y]	0
[CENTER_Z]	0
[CIR_PLANE]	G17
[COMMENT]	
[CURR_X]	0.0
[CURR_X_WCS]	0.0
[CURR_Y]	0.0
[CURR_Y_WCS]	0.0
[CURR_Z]	0.0
[CURR_Z_WCS]	0.0
[CUT_FEED]	0
[CYCL_1/TPI]	0
[CYCL_CLEAR+DEPTH]	0
[CYCL_CLEAR+INCR]	0
[CYCL_CLEAR]	0
[CYCL_CSINK_DEPTH+CLEAR]	0
[CYCL_CSINK_DEPTH]	0
[CYCL_DEPTH]	0

The Variables section of the Post-Processor Generator (PPG) dialog for our haas-blog.spm post definition file.

# Index

## - 2 -

- 2 Axis Hole Profiling 10
  - Cut Parameters 19
  - Posted G-Code 19
- 2 Axis Profiling 10
  - Cut Parameters 15
  - Posted G-Code 15

## - A -

- About this Guide 7
- Arc/Circle
  - Sample G-Code 37
  - Similar to Helix 37
  - Variables 37

## - C -

- Cutter Compension
  - Sample G-Code 43
  - Variables 43
  - What to do first 43
  - What to Know 43
- Cycles
  - Sample Deep Drill Cycle 47

## - D -

- Drilling 10
  - Cut Parameters 21
  - Posted G-Code 21

## - F -

- Feed Rate 33
  - Sample G-Code Control 34

## - G -

- General
  - G-Code Control 24, 32, 33

## - H -

- Helical 43
- Helical Motions
  - Sample G-Code 40
  - Understanding 40

## - M -

- Macros 9
- Motion
  - Example G-Code 36
- Multi Axis Motion 42

## - P -

- Post-Processor 8
- Post-Processor Generator 8
  - Circle 37
  - Cut Motion Start/End 46
  - Cutter Compensation 43
  - Cycles 47
  - Feed Rate 34
  - General 24
  - Helical/Spiral 40
  - Misc 50
  - Motion 36
  - Multi Axis Motion 42
  - Sample G-Code 24, 25, 28, 33, 34, 36, 37, 40, 43, 47, 50
  - Setup 32
  - Spindle 33
  - Start/End 25
  - Tool Change 28
  - Variables 52
- Post-Processor Generator Dialog 24
- Print Tool List 28

## - S -

- Sample G-Code
  - 2 Axis Hole Profiling 19
  - 2 Axis Profiling 15
  - Arc/Circles 37
  - Cutter Compensation 43
  - Drill Cycles 47

## Sample G-Code

Drilling	21
File	12
Flood/Mist	50
Helical	40
Tool Change	28
Sample Toolpath	10
Set Post	10
Setup	10
Spindle	
Example G-Code	33
Start/End G-Code Control	25

## - T -

## Tool Change

Example G-Code	28
First Tool Load Macro	28
Print Tool List	28
Tool Change Macro	28
Variables Used	28

## - V -

Variables	9
-----------	---